

# **Primatech H300 & H330 NAILERS**

## Guide for Replacement Parts



A new "L" feeder and guide assembly (*Patented*) was introduced in 1999. The redesigned assembly provides support to the cleat both front & back during striking, preventing bending on second or third stroke. Its open path allows clearing jams easily, without opening the tool.

The older configuration is no longer available and some parts have been discontinued. The UPGRADE kit [H-987](#) is available for tool manufactured before Jan 99.

The table below list all the parts of the H300 and H330 Manual Nailers:

- Most parts are compatible between the H300 and H330 Manual Nailers. Exceptions are noted below.
- Many parts were improved since the introduction of the H300 and H330 nailers. When obsolete, the replacement part number is given.
- The new "L" feeder and guide assembly introduces some incompatibilities. Check the [compatibility guide](#).

H-001	Body for 300 manual nailer	<b>H300 only.</b>
H-002	Body for 330 ratchet nailer	<b>H330 only.</b>
H-008	Plastic base	order H-108. Check for <a href="#">compatibility</a> .
H-013	Screw & washer	
H-018	Plunger for 300	order H-118.
H-019	Plunger for 330	order H-119.
H-020	Ratchet assembly	
H-021	Bumper	order H-922.
H-022	Dowel pin	order H-922.
H-024	Ratchet spring	order H-020.
H-027	Washer	order H-922.
H-030	Channel assembly	order H-130.
H-033	Pin	
H-034	Hitch pin	
H-036	Dowel pin	
H-037	Bolt	
H-038	Driving blade	
H-040	"T" gate/foot	order H-140 & H-241.
H-042	"L" gate/foot	order H-144 & H-343.

H-044	"L" foot (black)	discontinued, order UPGRADE kit <a href="#">H-987</a> . <b>Check for <a href="#">compatibility</a>.</b>
H-045	Spring	
H-046	Channel assembly for 300	<b>H300 only.</b>
H-049	"T" channel standard (grey)	for use with "T" gate H-241 only.
H-050	"L" channel standard (black)	discontinued, order UPGRADE kit <a href="#">H-987</a> . <b>Check for <a href="#">compatibility</a>.</b>
H-054	Grip	see also P-154
H-055	Spring & clip assembly	
H-058	Blade retainer	order H-158.
H-080	3.4 LBS hammer	
H-084	White rubber cap	<a href="#">see instructions</a> .
H-085	Replacement band for ratchet	<a href="#">see instructions</a> .
H-086	Hammer handle	
H-087	Reinforcement block	Check for <a href="#">compatibility</a> .
H-088	Adapter kit for 1/2" flooring	order H-188.
H-089	Angle adapter kit	
H-108	Plastic base	See <a href="#">compatibility</a> guide. Plastic base P-288 comes standard in some countries..
H-118	Plunger for 300	<b>H300 only.</b>
H-119	Plunger for 330	<b>H330 only.</b>
H-130	Channel assembly for 330	<b>H330 only.</b>
H-140	"T" foot (grey)	may also order H-144.
H-141	"T" gate (grey)	order H-241.
H-143	"L" gate (black)	order H-243.
H-144	Foot	will fit both "L" & "T" gates. See <a href="#">compatibility</a> guide.
H-150	"L" feeder channel	<b>Check for <a href="#">compatibility</a>.</b>
P-154	Handle grip	for tools manufactured after Sept 2005; <a href="#">see instructions</a>
H-158	Blade retainer	
H-188	Adapter kit for 1/2" flooring	see <a href="#">Technical Note</a> .
H-241	"T" gate (grey)	for use with "T" channel H-049 only.
H-243	"L" gate (black)	discontinued, order UPGRADE kit <a href="#">H-987</a> . <b>Check for <a href="#">compatibility</a>.</b>

H-288	Plastic base for <i>metric</i> floorings	includes shims and P-986 self-adhesive base.
H-343	"L" gate (black)	<b>Check for <a href="#">compatibility</a>.</b>
H-900	Discontinued	
H-922	Part Kit (H-021 H-022 H-027)	
H-930	Discontinued	
H-938	Box of 25 driving blades	
H-987	Feeder & guide <b>UPGRADE</b>	See <a href="#">instructions</a> . See also <a href="#">compatibility</a> guide.

---

## COMPATIBILITY GUIDE

---

All H300 & H330 nailers manufactured before Jan 99 use a conventional feeder & guide assembly. The parts below are not compatible with the new feeder & guide assembly. These parts have been discontinued, but the H-987 UPGRADE is available to convert existing tools to the new configuration. Contact us for more information.

---

H-008	Plastic base	Not compatible with H-087 reinforcement block, but it can be easily modified to fit (see <a href="#">Technical Note</a> ).
H-044	Foot	Not compatible with new H-087 reinforcement block.
H-243	"L" gate	<u>Not compatible</u> with new feeder channel H-150.
H-050	"L" feeder channel	<u>Not compatible</u> with new gate H-343.

---

## H-987 UPGRADE

All H300 & H330 manufactured since Jan 99 use a new feeder & guide assembly. The **H-987** kit allows to install the new configuration on tool manufactured before Jan 99. It consists of all these parts:

H-108	Plastic base	Will fit <u>all</u> H300 & H330 nailers.
H-144	Foot	Required for new H-087 reinforcement block.
H-343	"L" gate	<u>Not compatible</u> with old feeder channel H-050.

H-150 "L" feeder channel Not compatible with old gate H-243.

H-087 Reinforcement block Requires H-108 (or modified H-008), H-144, H-343 & H-150.

---

© [Copyright](#) 1996-2005 Primatech. All right reserved. [Disclaimer](#). Comments to [webmaster](#).